

20
University Premium

19 August 1979

— to —

18 January 1980

Page 1.

18/1/80

Tour of building

s 47F - privacy

Considered

- ✓ wall ducting, fans, from R/LR
area - OUT
- ✓ contaminated
benches
floor tiles
floor board (esp. R/LR repair room)
— OUT

(from here on THS/IM took over)

End of Stage 1


20/12/79

Rm Lab-VI

Object of visit was to proceed with removal of waste & 'clean up' as much as poss^{ble}.

Relevant work, noted here (R, THS):

- Collected all remaining mercury. To go to Yallambrie.
- Dismantled mercury ('sucker') remover: placed vacuum pump + motor on small trolley.
- Emptied vacuum cleaner into bag & to active waste drum. Left clean (new) bag in it.
- Monitored items (Victoreen 470 A)
 - 1/ vac. cleaner: max 8 mR/h (near intake)
 - 2/ ducting from Ra
 - 3/ repair room: max 7 mR/h (near flange, as before)
 - 4/ waste bin: max 10 mR/h (spot marked 'X' on drum)
- Covered waste bin with 'waste' plastic bag - a firm fit →



lift vac cleaner
ducting
waste bin

all in strong room & locked the door.

• Victoreen 470 A:

- 1/ level in Ra repair room: 0.7 to 0.9 mR/h (along median line)
- 2/ in geom. centre strong room: 1.0 mR/h

Certain items, found to be 'contam' were broken up & removed with waste. Total items---- filled one truck.

s 47F - privacy

Left \approx 11.35 after turning off all fans, in main building & Rn area - believed best to leave off over holidays. Can also check Rn build up (there may be some - note items left in Strongroom, 'contam' on floor Rn repair room ---).

Personal monitor: I did not use a p.m.; but on past experience my dose would not exceed 2mR. So, take 2mR

Total: s 47F - privacy 46 mR.
22 mR)

Note added 21/12/79.

TNS called at this b'g in am & closed all doors between main building & Rn area - object. to assess build-up of Rn (over a few weeks?)

18/12/79

s 47F - privacy


Ra Lab. V
Ra Repair Room VII

Overalls.

Respirator, where indicated.

Work done:

- Removed ducting in Ra. repair room by undoing bolts holding ducting at flange.
- Sealed both ends of ducting removed - covered with heavy duty plastic & used tape to hold.
- Cleaned any dust from inside remaining ducting using vacuum cleaner extension - cleaned to just above ceiling. (Wore respirator for this).
- Sealed end of remaining ducting by covering with heavy duty plastic & used tape to seal 3 accessible sides.
- Used vacuum cleaner to remove all dust on wall behind ducting removed. (Also removed dust on floor of room.)



18/12/79

2

- Turned ^{large} lead 'bricks' over + cleaned (scraped) 'deposit' off surfaces. Bricks now clean on all sides. Lead scrapings collected in vac. cleaner. Floor cleaned.
- Removed remaining bottle of mercury - covered in oil. (Took to Yallahs & stored with the rest.) The only Hg at Uni HCL is the small amount in the bottle used as the reservoir when collecting Hg by vacuum pump.
- Left dusting, tin Rf waste, vac. cleaner, all in strongroom. This will be a 'hot spot' - should be removed before next general survey begins.
- Left fans on in main building but turned fans off in Rn area. (The latter fans were off during the removal of the dusting - considered safer, & less likely to spread dust.

Personal Monitors:

HPT 3746

HPT 3748

s 47F - privacy

1mR

10.00 to 11.30

1mR

"

Total to date:

s 47F - privacy

45mR

Ra Repair Room:
Stage 1 completed
18/12/79

Rm Lab. IV
Ra. Repair Room VI

29/11/79

s 47F - privacy

Overall, looks -- as for 15/11/79
Monitor. Victorium 470A
'Panoramic'

Work done (much concurrently):

- Removed the metal supports from the rollers on the overhead rails in the Rm Lab.
- Removed remains of supports from the lead screens (previously rolled in front of the Rm plant) - cut off flush with screens.
- Cleaned cupboard in Rm Lab - removed wax, bottles -- & used vacuum cleaner over the inside.
- Lifted lead tiles on floor until could find no more mercury & removed all mercury found -- checked rest of floor.
- Cleaned all 'available' surfaces of the two large lead bricks removed from glove box. Used rasp & chisel. Not effective. Collected all bits with vacuum cleaner. Left only 'underneath' faces still to be done - one brick (marked) is still $\approx 3 \text{ mR/h}$ on underface. Rest of bricks $\approx 0.5 \text{ mR/h}$ (could be due to scattering underneath -- scatter -- ?)
- Checked duct in Ra repair room. There is a 'hot spot' (only one?) on front face just at or below the flange: max 7.8 mR/h . Approx 6 mR/h in vicinity, decreasing to 1.5 mR/h at base. Tried to undo bolts but too much paint on them. Will have to remove using hacksaw.
- Inspected old vac. pump - decided no mercury in it.

29/11/79

- Decanted all mercury (except a small amount of very 'oily' mercury held in bottle) into 4 winchesters. These were removed to Yallambrie.
- Under roof, above Rn lab. General level $200 \mu R/h$ + approaching Ra repair room went to $500 \mu R/h$ +. Will increase as dusting from that room approached.
- Sorted items on floor according to whether 'contain' or not - used 30 cps or PCM 5 as 'limit'

Personal Monitors:

s 47F - privacy

21/11/79

s 47F - privacy

Radon Lab III

Overall, looks, as of 14/11/79
Monitor Victorian 470 A 'Panasonic'

Work done: (some concurrently).

- Cleared sink of sludge & mercury in U bend.
— could not undo X -- so removed whole sink to gain access to U bend & replaced after cleaning. Bend clean except for the Hg which has amalgamated with the brass.
- Removed waste wood from the repair room
— to 265 Spring St later today.
- Emptied the vacuum cleaner bag and base of v.c. Replaced. Monitored v.c. — man close to surface 15 mR/h & along hose varied from 1.5 to 3 mR/h as main body of v.c. approached.
- Removed old mercury sump, framework & supporting bend to workshop area.
- Removed 'lower' vac. pump assembly, which was known to contain mercury after serious accident in which Hg was pumped through it. (Pump useless. motor should be V)
Drained pump — collected (prob.) 100 mL Hg.
[Opened pump up & drained as well as possible.]
Pump & bits into plastic bag for disposal.
- Removed mercury from floor -- etc.
went under floor to area under

s 47F -
privacy

2/11/79

Ran pump & recovered 'vapour trap' (a glass flask Δ) - about $\frac{1}{4}$ full Hg. Found stopper at top had been forced out & Hg on ground. Using 'sucker' and compressed air line s 47F - privacy was able to recover most of it. (It was poss^{ble} to pass these lines through existing holes in the floor). s 47F - privacy spent $\approx 1\frac{1}{4}$ h doing this. (Re 'upper' vac. pump assembly was used to activate 'sucker' at all times)

- Removed lead screens from overhead roller supports - left leaning against wall.
- Removed some floor tiles - collected 'stray' mercury. Some Hg is well inside deep floor joints - cannot reach with sucker.

Personal Monitors:

(Through oversight, did not wear them during morning. From past experience & having regard to nature of work done, can assume dose to s 47F - privacy and myself would have been ≈ 1 mR)

During afternoon, used monitors:

#PI 3746	s 47F - privacy 2 mR	Total: $[(2+1) + 39] = 42$ mR
HPI 3747 ₍₁₎	s 47F - privacy 5 mR	$[(5+1) + 15] = 21$ mR

(had been dealing with active waste)

(Ra
Isent)

15/11/79

s 47F - privacy

Radon Lab. II
& Ra Repair Room V

Morning + afternoon
(10.05 to \approx 16.00)

Overalls, boots, as for 14/11/79

Monitor: Victoreen 470 A 'Panoramic'


Used monitor: above mercury tank under Ra 'pump'

0.15 mR/h

liquid air trap on last stage of Ra
pump (most active part) 0.25 mR/h


glass tube leading to strongroom,
above Ra pump 0.5 mR/h.

A/ Dismantled Ra pump, from top downwards.
Glass parts put in drum & broken up.
All framework above the pump removed.
Glass tube leading to strongroom removed.
(this contained some mercury)
The line included a glass 'trap'



This was 'active': 3 mR/h.

Also line appeared to have been
joined at some time:



Found easiest to break glass tubes using
file - cut 'inch's break same way. Few
failures.

When all remains of the pump were
in the drum the exp. rate on outside
surface was (max) $\approx 1.3 \text{ m}^2/\text{h}$
With the glass 'trap' removed $\approx 1.2 \text{ m}^2/\text{h}$

B/ Mercury tank under pump.

Removed top plate - no difficulties.
Top of mercury very dirty - 'scum';
flakes of metal (rust) from under-
surface of top plate; 2 pieces glass
tube + some glass bits; some (little)
grease; bits of cork.

Cleared mess away from 1 corner
& placed cardboard between tissues, on
top of remaining surface to hold
scum from floating about. Then -
used beaker to dip Hg from 'clean'
corner & pour Hg into wide
plastic funnel set in top of
'winchester' bottle. Filled ~~the~~ 5
'winchesters', each about $\frac{1}{3}$ full. Final
collection of mercury from tank &
from 'safety tray', floor... of
'suction' into existing bottle, using
top vacuum pump of the plant.

Very effective means of collection.

During work found remarkable
quantity of mercury lying under
tank - origin?

Lifted some bins. near pump to see

15/11/79

3

whether we can gain access to 'vapour' trap under floor - prob. contains Hg. Answer - no. Will either have to go under floor or raise floor boards locally - latter seems pref^d.

Note Hg appears inactive. Measured between tops of 4 w'chisters (with Vidarum) at Yallambie - no response > background ($\approx 0.05 \text{ mR/h}$)

All 'scum' - etc - left in tank tipped into tray, & thence into drum with waste. Tank & tray now clean.

✓ In Ra repair room: cut remains of old bench into shorter lengths & split - easier to dispose of, & safer.

Digital Monitors:

s 47F -
privacy

HPI 3748

1 mR

Total
(to date)
39 mR


HPI 3746

1 mR

15 mR

Note of the 'lower pump' in Ra plant does not work. Motor appears v. Belt 'slips'.

✓ The small vac. pump in Ra lab. does not work, ~~now~~ does motor (?) Whole seems 'jammed'.



VENT CHAMBER

GROUND FLOOR PLAN

5/11/79
s 47F
privac

Released by ARJIS under the Freedom of Information Act

14/11/79

s 47F - privacy

Ra/Rn Area: Rn Lab I

Used 'old clothes' and
white overall (AWRE),
+ R. boots, O'shoes.

(morning
08.35 to 10.05)

Took photographs (5) of Rn pump. (Instantatic
(note added - there are in 'archives') + flash.)

Removed one bolt from top of mercury
tank under Rn pump. (There are 36 bolts)

Removed 'plug' from top of mercury tank
& tested depth of mercury. ~~XXXX XXXX~~

Measured dimensions (O.D.) of tank ~~as~~ as
55 cm X 34 cm X 9 cm

Depth mercury 4.5 cm - tank: half full.
Vol of 8.4 L. Mass of Hg (8.4 X 13.5) = 114 kg (\approx 50 lb)

Inspected Rn pump + tank. Appears to be
no obstacle to dismantling whole.

Remove Hg from tank by ('siphon') suction
& (finally) remove top of tank.

Floor covering: tiles.

Pump outlet - seems to go under floor
& no upward return!

Wood - monitor for active areas
- split
- saw a break.

— to bags.

Digital Monitor: HPI 3748 1mR

Total
38mR

30/10/79

s 47F - privacy

Ra Repair Room IV

(morning)
≈ 4h

Changed, as for III on 24/10/79.

In Ra repair room broke up glove box.
Moved remains out to leave room for later work. Cleaned floor with vac. cleaner.

Emptied vac. cleaner. Before, max ≈ 100 mR/h on surface; after, max ≈ 25 mR/h.

Moved trolley into repair room & placed against bench. Trolley ≈ 1cm higher than bench top. Used 2 plastic bags to cover adjacent areas on trolley & maneuvered lead bricks on to them. Moved trolley out of repair room & left in Rn Lab.
One lead brick has 'hot' area on one corner ≈ 10 mR/h (γ) at surface.

Checked top bench with monitor. MIN 8 mR/h, MAX 27 mR/h
AV. ≈ 15 mR/h

Scraped 'hottest' areas & removed dust with vac. cleaner.

Removed all dust ^{and debris} from inside cupboards.
Checked with monitor. Found one 'stain' on top shelf towards window end: 8 mR/h.
Scraped to remove surface. Removed dust with vac. cleaner. General level in cupboard was ≈ 2 mR/h.

Broke up bench top - split into several lengths. Removed temp. outside room.

30/10/79

Broke up & removed cupboard. Cleared dust as possible from walls, etc. Found no active 'remnants' near or under. Cleaned up all wood -- removed outside temp.

Checked floor - found some active areas. Removed all dust & debris. Active areas associated with stains, but most of stains on floor are not active.

Marked 'hot spots' with chalk & gave identifying letters:

Area:	A	B	C	D	E	F	
Exp. Rate ($\frac{mR}{h}$)	10	20	15	16	6	6	($\begin{matrix} \text{max} \\ \text{values} \\ \text{'surface'} \end{matrix}$)

Exposure rate in room:

In doorway $\approx 1 \text{ mR/h}$, + moving monitor at waist height along median ^(E-W) line of room found rates 1 mR/h to 0.8 mR/h . - seems remarkably constant.

Outside, over preparation bench next to windows in East wall rate fell to 0.2 mR/h . [on 10/10/79 before work done in room, exp. rate was $\approx 12 \text{ mR/h}$]

Checked vacuum cleaner with monitor: ~~max~~ (surface) MAX 30 mR/h & rest 20 to 25 mR/h

Moved remains of bench & cupboard back into room. Moved trolley with lead bricks back into room. Also, vac. cleaner and all 'bits', and tools used.

30/10/79

Digital Monitors.

s 47F -
privacy

HPI 3746 6mR

HPI 3747 4mR

Total to
date
37mR

14mR

Next Visit

Photograph Rn pump --- (flash, etc.)

Empty vac. cleaner, as before. measure ---

monitor
+ empty
later.

→ Inspect lead brick... clean (?)

[Hot spots only?
scrape?
sandblast?]

-OR OUT as scrap?

Wood - for disposal.

MONITOR

Remove Rn pump. (Glass file) (overhead line)

" mercury -- monitor tank --- (sludge?)

" " under floor

Residual Hg (benches floors).

may have to remove lino. ---

+ search for Hg and
hot spots of contam.

Generally clean up Rn lab., strong room.

Hot spots elsewhere - clean Rn benches + workshop floor

Ducting - Rn repair room
- Rn labcheck
Rn[Remove non-fixed contam
- Hg.]

Released by ARDANSA under the Freedom of Information Act

24/10/79

s 47F - privacy

(Morning)

La Ripari Room III

Changed to old clothes &
put on white (AWRE) coveralls,
with rubber boots, gloves (2 pairs of
heavy work) and respirator (full face).
Used as necessary.

Emptied bag in vac. cleaner into sealable plastic
bag keeping 'dust' confined. This dust v. active.
Cleared blockage (rubber stopper) in entrance to
vac. cleaner hose. Cleaner operating well. Used
1) brush 1") open aperture (1/2") on long extension.

(1) checked bench with monitor. Found 'hot' area
near East end - no definite source; seemed
to be embedded in dried material fixed on
bench surface.

(2) cleared dust off whole bench & off
lead bricks, & off walls where necessary & off
part of floor where must walk.

(3) removed (plate) glass window from glove box
& removed dust from box (v. little there). Decided
to leave box intact for present.

(4) scraped top of bench, esp. where monitor
indicated active material. 'Hottest' area 220 mcp/h
but reduced to ≈ 20 mcp/h upon scraping. Some
general contamination all over bench.
Scraped quickly around lead bricks. Scraped
more bench - general clean of surface. All loose
dust removed.

Decided to leave until next visit. Check on
vac. cleaner gave 180 mcp/h - again active.

Check with monitor showed levels consid.
decreased.

Total 'dose'
accum.
to date

Digital monitors

S 47F -
privacy

N₂ HPI 3746 8 mR

31 mR

No HPI 3748 3 mR

10 mR

(~~17~~ Monitor carried in pocket of trousers, L.H. side.)

Next visit

- (1) empty vac. cleaner as before
- (2) move wood out of repair room
- (3) scrape, clean lead bricks
- (4) remove lead bricks - trolley
- (5) close air vent overhead and
remove dust from ducting, if poss.
- (6) clean, scrape bench--
- (7) " dust off floor
- (8) " " from cupboards (most of it)
- (9) knock up bench ready to remove.
- (10) complete clean. of cupids

check residual contam. - levels of mR/h.

Review: action still req'd, [esp. cupids - should they
be removed -- broken up -- ?]

yes
← because
may be RAs
not behind,
even under

(11) remove cupboards

(12) clean behind (esp?)

S 47F -
privacy

17/10/79

s 47F - privacy

Ra Repair Room II

Changed to old clothes and put on white (AWRE) coveralls, with rubber boots, gloves + (most of time) respirator (full-face).

Radium-repair room

Checked vacuum cleaner - operating well. Used v.c. with brush on end of long extension to

- (1) clean up dust on bench + part of outside wooden cowling.
- (2) clean up dust inside glove box - v.c. suddenly ceased to 'suck' properly - blocked? Some 'pull' left but not enough to be useful.

From glove box removed a waste, piece glass tube; razor blade, one glass flask $\approx 150 \text{ mL}$ - This found to be v. active (100 mR/h near surface)

- (3) In consultation with J.S. demolished wooden section of glove box & removed all from bench - left on floor. Inside of box (on walls) seemed remarkably clear of dust - this mostly on bench. Was able to slide large lead blocks on bench, but very heavy. Bench now 'open', but still dusty at East end. This end is v. active - monitor to 1 R/h. (!) Demolition took $\approx 20 \text{ min}$.

Decided to leave 'as is'. Opened ^{overhead} air duct, which I had kept closed during clean up + demolition. (It is normally left open to assist removal of Rn.)

17/10/79

Check on vacuum cleaner gave reading
 $\approx 200 \text{ mR/h}$ near bottom - v. active.

Check with monitor shows that with
 v. cleaner removed (to strongroom) levels
 of exposure rate are about half what they
 were near open door, in room.

Digital monitors.

s 47F -
 privacy

No.	HPI	3746
No.	HPI	3748
No.	HPI	3747

At end
 of operations
 10 mR
 4 mR
 1 mR

Removed 2 more winchesters, $\approx 1/3$ full, of Hg, to
 Yallambrie - stored with rest.

Next visit

✓ Take (i) old clothes, - (ii) tissues to clean respirators
 (iii) an axe⁽⁺⁾, to break up bench.
 - (iv) brush(?)

✓ and (v) for vac. cleaner (is it blocked?)

✓ (1) clean up remaining dust on bench
 + floor, if poss. using vacuum cleaner.

x (2) remove bench - note E. end v. active

✓ (3) leave all wood in room pending removal.

[NOTE: lead bricks are too heavy to lift off bench
 but can slide about, with effort.]

x (4) monitor inside of wooden coving - active?

x (5) Poss. - dust from vent.

10/10/79

Next visit / 17/10/79

Takes

- ✓ a) Remove more Hg — ~~1st~~ (bottles)
- ✓ b) Remove dust from ^{glove box} floor --- in
Ra repair room: bag from vac.
cleaner OUT as waste. (High level).
- c) Inspect glove box — how best
decontaminate store as waste. Remove
lead blocks — store — (?)
- see
note
17/10/79
↓
Late decontaminate glove box — must use full
protection for b/c) above.

Present views:
11/10/79

- 1) prob. all. sig. contam. in
glove box
- 2) clean up dust ---
+
- 3) decontaminate glove box — store as waste.
- 4) survey ~~at~~ levels after 2/3) above

[Prob. recomm. decontaminate all S. end building
+ poss whole S. wing.

NOTE Hg: under bench? in 'out'
under floor?]

R-a Repair Room I

10/10/79

s 47F - privacy

Preliminary Assessment of β .

Afternoon

1. Measured exposure rate in room
(Monitor: Victoreen 470A 'Panameric')
outside: S. wall (mean ≈ 12 mR/h - seems to
be opposite bench in glove
box)

inside: N. wall: increases from door
end towards E. wall. max 30 mR/h

in doorway 7 mR/h

in glove box - near (door) lead
brick on bench 300 mR/h (mean)

Digital monitors: personal monitoring.

s 47F -
privacy

monitor HPI 3748. At end of operation 13 mR

" HPI 3746. " " " 3 mR

Dust samples: collected from bench
walls, & inside glove box - in plastic
containers, marked. Also removed glass &
small items from inside glove box.

s 47F - privacy

In addition to this 'radioisotopic' work, we removed some of the mercury found in the radon lab.

This was in bottles. Covered by placing in plastic bags, etc. At Yallahie, they were placed in wire cage in 'waste' area so that loss or damage is unlikely. The mercury will have to be checked for radioactivity. The bottles will have 'active deposit' on the outside.

There is much more mercury to come - including mercury in reservoir of radon pumps.