000(4)(")	
s 22(1)(ii) irrelevant	
	15/3/02 18
_	00
=	143 pr 0
	Need
	1800 FH
	BH RAM GE
	17/3/02 10
	0
	1830 FH40
SPECIAL NOTE TO HIFAR APS	GEN
INSTRUCTIONS FROM DUTY DSC.	16/3/02
A release of fission products occurred today	10/3/CA
at the 823 pond during fuel-rod cropping.	
the area was affected by high radiation dose rates as a result, viz	
dose ratio as a roun, viz	17/2/02
pond ledge level ~ 100 p.Siph AMBIENT	4
pond chest level - 56 pSv/k AMBIENT.  pond Gittration (at wall) ~ 40 mSv/h @ Contact	
Tomorrow the duty Soss will switch Gitration	
to the new ion-column outside B23 ( corner of	
building near GATRI).	
the DSC has requested (ie instructed) the	
duty HIFAR HPS at each shift to monitor	·
the radiation dose rate at these points:	
and ledge labore cropping pond water) level	<b>/</b>
pond ledge (above cropping pond water) level, pond above water at chest level,	<b>/</b>
· wall fittration equipment,	16:3:02
· external ion column,	0030
and record results in the HIFAK HI lag.	
these checks should be made atleast over	1
the weekend and until the DSC instructs	1
11 - 0 180	
Summerize measurements on page apposite.	

	$\vdash$	SHIFT	POND LEDGE AMBIENT	POND CHEST AMBIENT	WALL FILTER @CONTACT	EXTERNAL ION- COLUMNIEC	
15/3/02 1800		AS ADVISED BY DSC	100 µSv/h	50 ps/h	40 mSept		
0030		SATURDAY M	50a5jh-1	3045vh"	50 ms/h		=
43 pr 09:00	X	SATURDAY DU	90pch1	30,001	50ms/5-1	~ 1p5v/4	
13:30	Ď	(4)	7	30,5h-1	50msil	€ 2 µSv/h	
1800 FH40F1		SATURDAY E	98 ps/h	45 p.Su/h	52 mSv/h	=3 prSo/h	
BK RAM GENE-1	_	Calmara AA	500 pselh	230 psu/L	off-scale	< 1 pSv/h	_
13/02 100 8	$\vdash$	SUNDAY M	70 ps/h-1	50 ps/h"	62msvh		
9/8		SUNDAY D	511 psv2	200/05/6	off scale	0.64544	
09:30		1	Bould	370 541	52 MM	5 MSV 47 58 MSV L	<del></del>
830 FH40F1	Н	SUNDAY E	1700 ps Vh	13 psoph	off-sceake 47-7mSv/h	=3 ps/4	
GENE-1			750 usyl	250 ps/h	off-scale	=2µSv/h.	
16/2/02/02:00		sel Inlet pip	T ^ 1 V A/A		et pioe 1		GAT
и 10:0	بـ ا	HA CLEAR PIP	ES FAST SIDE	BADUALL	3 m 1-1 R/S	270 col - 1 / Bas	<u>. Ge</u> dh
	1	1800, 16/3/0	2) CLEAR PI	PES EAST S	DE POND W	PALL	
						BM RAM GENE	-/
17/2/02 09:30	Cı	EAL PIPES E	. ENO OF PON	DWALL 4.10	EMELL BY:	220 ps Lake	610
4 ~	1/1	LET PIPE ION)	COWMN 29	Open Bly 6.7 jul	IN S (NEAR BUR	M A Im Hancou	MAT
	L			, , ,			
				·			
					<del></del>		
<del></del> -	-						
<del></del>	<u> </u>						

Two Survey points. point 1 over water (approx 18") above same laping point 2 over water (approx 18") other end of

cropping pond.

point 2 @ 0030 = Top Filter =

bottom filler

point 1 @ 0030 = 50 25vh" point 2 @ 0030 = 30 25vh"

= 50 mSvh1 = 1 mSvh1

, 00	SATURUAY 10/05/2002	Ì
S	22(1)(ii) irrelevant	
		<u> </u>
(1850)	Copy survey to RSS	
	s 47E personal	
1700	Phoned DSC - Confirmed the	
N.B.	(a) The 4 areas for HI survey surrounding the post.	
	These areas are (i) POND LEDGE LEVEL - area	
<del></del>	These areas are (1) 1 out thinhest dose rate	
	above cropping pord water. Highest dose rate	
·	recorded whilst moving detector along length	
	of Cropping ports.	
<u> </u>	He height of the good wall.	
	(II) POND CHEST LEVEL = STATE	
	to (i) above however hold the detator at	
	your chest height.	
	(III) WALL PILTRATION LEGIT TELE	
	measure the contact dose rate at the bowl	
	of the 2 filters (the highest dose not is	
	assembly from the top nost filter).	
<u> </u>	(iV) EXTERNAL ION COLUMN -	
,*	measure the contact dose rate of the	
	in-service column (2 column's are part of	J
!	plant — both adjacent to each other outside	
	B23 wall near GATRI). Currently the	
	B25 wall near UAIRI). Use growing books	
<u>;</u>	B/ dose rate is	1
	top and bottom pipe connection flanges.	
	(b) Health Physics dose rate checks should be made	
<u> </u>	at each shift - Once per shift - as acous	1
	8 hour intervals. DSC has confirmed with	1
4	s 47F personal the frequency of measurements	
	(ignore previous e-mail instruction indicating	1
ŧ	Us housen checks).	1
	(c) As indicated at page 49 of this log, record	
	magtivener cosult in this log AND	
}	summerine measurements in tabulated form	
	at page 50. NoTE: Do not change	
<b>M</b>		Table 1

the structure of the (page 50) table \_ unless in with the DSC authorised and in consultation The DSC authorised the use of liquid paper to rearranged data placed incorrectly. survey of the pond area record any in this log and summerize page 50 in the space below If space at page 50 runs-out then start a new summary on a

When I surveyed B23 I used 2 dose rate makers (i) FH 40FI high range of results below Surveyed radiation dose rates at B23 pond area as required by DSC Resulto : -POND LEDGE ~

98 usuph AMBIENT FH 40 F1 GENE-1 500 usulh AMBIENT 45 pSoft AMBIENT POND CHEST ~ FH40 FI 230 pSV/h AMBIENT GENE-1 WALL FILTER ~ FH40F1 52 MSV/h @ CONTRACT GENE-1 off scale @ CONTACT EXT. ION COLUMN ~ FH40F1 < 3 pSu/h @ contract < 1 ps/h @ contract. GENE-1

When finished at the pand area I left the cage set askew to the pond. This quicker HPS entry and exit. Informed and got the duty Soss to the surrounding area is traffic 'Ahank-you to 'outside' ROthe B'23 survey

NOTE

1800

Sunday 17/3/92 22(1)(ii) irrelevant 100 HP Survey of B23 pand as per DSC instructions Pond-level 82 70 perh 1 8/82 511ps/1 Sond cheatlened 8 = 50 ps/ 1 8/82 200 ps/ 7. Filter 82 62 rsvhil 1/82 Apt scale 10n-col 82 0.5 psuh 10 \$/82 0.6 psuh (c) 22(1)(ii) irrelevant

s 22(1)(ii) irrelevant

# liconfidence

# **Gamma Spectrometry Analysis**

### January 2003

Due to the design of facility ponds and buildings, small birds periodically enter the confines of the facilities. Because the pond water contained relatively minor levels of radioactivity, this was not a concern over the years. In March of 2002, the water in one pond was contaminated with fission product activity. As a result of concerns stemming from this contamination, analyses were performed on dead birds found in the area of interest.

Because a variety of wildlife live at Lucas Heights, it is customary to find dead birds on site. Of five birds collected, two were identified as contaminated to a minor degree. These two birds were provided to the HIFAR Chemist, who was requested to perform gamma spectrometric analysis to determine the likely source of the contamination. In both cases the analysis was purely qualitative as the birds presented an unusual geometry, which made quantitative analysis difficult. However the relative sizes of the peaks are published with the Region Of Interest (ROI) data present in this report. In addition, it should be noted that the analysis was performed on the whole of the bird and as such no distinction was possible between internal and external contamination.

The spectra obtained from this analysis (using EG&G Ortec's MAESTRO-32) indicated the presence in trace amounts of mixed fission products such as <sup>134</sup>Cs, <sup>137</sup>Cs, <sup>144</sup>Ce, <sup>131</sup>I, <sup>103</sup>Ru, <sup>144</sup>Pr, <sup>95</sup>Zr, <sup>95</sup>Nb and <sup>140</sup>La. In addition to the mixed fission products, the first spectra also indicated the presence of <sup>41</sup>Ar, however this is likely to be part of the background spectrum due to the emission of <sup>41</sup>Ar from HIFAR.

The presence of the mixed fission products indicated that the birds had been in contact with the contaminated pond. It was noted that Bird No.1 showed higher levels of contamination than Bird No.2 As there was no accurate efficiency data available for the analysis (due to the abnormal geometry), estimations of activities present in Bird No.1 have been made on the efficiency curve obtained from of a 10ml vial. A summary of the estimations of the total activity present (internal & external) are presented in Table 1 and the calculations are available in Table 2.

Table 1. Summary of Estimated Total Activity

Radionuclide	Estimated Activity (Bq)
<sup>144</sup> Ce	2283
<sup>134</sup> Cs	17
<sup>137</sup> Cs	23
<sup>131</sup> I	4
<sup>95</sup> Nb	17
144 Pr	2476
<sup>103</sup> Ru	4
<sup>95</sup> Zr	10

Inconfidence

It should be noted that  $^{90}$ Sr is also a mixed fission product, but as a pure beta emitter it would not have been detected in the gamma spectrometry analysis. It is assumed that  $^{90}$ Sr and  $^{137}$ Cs exist in approximately a 1:1 ratio.

No adverse health effects would be expected from this degree of contamination. A cover has since been installed over the pond to minimise the possibility of further issues in this regard.

### s 47F personal

Radiation Protection Adviser May 29, 2003

Detector #1 ACQ 08-Jan-2003 at 15:54:16 RT = 5086.6 LT = 5000.0 DSPE-218 bird1 ROI # 1 RANGE: 631 = 79.19keV to 653 = 81.94keV AREA : Gross = 8889 Net = 5186 +/- 125 CENTROID: 641.88 = 80.55 keVSHAPE: FWHM = 0.99 FW (1/5) M = 1.55ID: Ce-144 at 80.12keV Corrected Rate = 64.82 + /- 1.56 cA RANGE: 975 = 122.13keV to 997 = 124.88keV ROI # 2 AREA : Gross = 5307 Net = 665 +/- 117CENTROID: 986.04 = 123.51 keVSHAPE: FWHM = 0.46 FW (1/5)M = 1.42ID: Ce-144 at 133.53keV Corrected Rate = 1.23 + /- 0.22 cA ROI # 3 RANGE: 1057 = 132.37 keV to 1081 = 135.36 keVAREA: Gross = 75444 Net = 65352 + /- 311CENTROID: 1069.26 = 133.90 keVSHAPE: FWHM = 1.06 FW (1/5) M = 1.65ID: Ce-144 at 133.53keV Corrected Rate = 121.02 + /- 0.58 cA ROI # 4 RANGE: 1582 = 197.90 keV to 1608 = 201.15 keVAREA: Gross = 1916 Net = -136 +/- 83 CENTROID: 1594.76 = 199.49 keVSHAPE: FWHM = 0.23 FW(1/5)M = 0.38ID: U-235 at 202.12keV Corrected Rate = 0.00 + / - 1.66 cA RANGE: 2905 = 363.09keV to 2935 = 366.84keV ROI # 5 AREA : Gross = 870 Net = 389 +/- 48CENTROID: 2917.93 = 364.70 keVSHAPE: FWHM = 1.28 FW(1/5)M = 1.98ID: I-131 at 364.48keV Corrected Rate = 0.10 + /- 0.01 cA ROI # 6 RANGE: 3725 = 465.50 keV to 3759 = 469.75 keVAREA : Gross = 481 Net = 26 + -47CENTROID: 3742.28 = 467.66 keVSHAPE: FWHM = 0.16 FW (1/5) M = 0.32ID: Cs-134 at 475.35keV Corrected Rate = 0.36 + / - 0.64 cA ROI # 7 RANGE: 4077 = 509.47 keV to 4113 = 513.96 keVAREA : Gross = 851 Net = 290 +/- 56CENTROID: 4096.04 = 511.84 keVSHAPE: FWHM = 0.76 FW (1/5)M = 1.48ID: Ru-103 at 497.08keV Corrected Rate = 0.07 + /- 0.01 cA ROI # 8 RANGE: 4817 = 601.91keV to 4855 = 606.66keV AREA : Gross = 966 Net = 641 +/- 49 CENTROID: 4837.92 = 604.52 keVSHAPE: FWHM = 1.33 FW(1/5)M = 1.91



ID: Cs-134 at 604.66keV Corrected Rate = 0.13 +/- 0.01 cA

- ROI # 9 RANGE: 5273 = 658.88keV to 5313 = 663.88keV AREA: Gross = 1813 Net = 1458 +/- 59 CENTROID: 5294.06 = 661.51keV SHAPE: FWHM = 1.39 FW(1/5)M = 2.20 ID: Cs-137 at 661.62keV Corrected Rate = 0.34 +/- 0.01 cA
- ROI # 10 RANGE: 5552 = 693.74keV to 5592 = 698.74keV AREA: Gross = 2630 Net = 2452 +/- 59 CENTROID: 5572.55 = 696.31keV SHAPE: FWHM = 1.64 FW(1/5)M = 2.38 ID: Pr-144 at 696.49keV Corrected Rate = 32.91 +/- 0.79 cA
- ROI # 11 RANGE: 5775 = 721.61keV to 5815 = 726.61keV AREA: Gross = 477 Net = 279 +/- 37 CENTROID: 5791.64 = 723.69keV SHAPE: FWHM = 1.70 FW(1/5)M = 2.48 ID: Zr-95 at 724.18keV Corrected Rate = 0.13 +/- 0.02 cA
- ROI # 12 RANGE: 6033 = 753.85keV to 6075 = 759.10keV AREA: Gross = 483 Net = 297 +/- 38 CENTROID: 6055.28 = 756.63keV SHAPE: FWHM = 1.04 FW(1/5)M = 2.25 ID: Zr-95 at 756.72keV Corrected Rate = 0.11 +/- 0.01 cA
- ROI # 13 RANGE: 6101 = 762.35keV to 6143 = 767.60keV AREA: Gross = 1261 Net = 1075 +/- 47 CENTROID: 6127.05 = 765.60keV SHAPE: FWHM = 1.54 FW(1/5)M = 2.29 ID: Nb-95 at 765.82keV Corrected Rate = 0.22 +/- 0.01 cA
- ROI # 14 RANGE: 6347 = 793.09keV to 6389 = 798.34keV AREA: Gross = 670 Net = 484 +/- 40 CENTROID: 6367.01 = 795.59keV SHAPE: FWHM = 1.66 FW(1/5)M = 2.26 ID: Cs-134 at 795.76keV Corrected Rate = 0.11 +/- 0.01 cA
- ROI # 15 RANGE: 10326 = 1290.61keV to 10378 = 1297.12keV AREA: Gross = 1584 Net = 1522 +/- 44 CENTROID: 10347.69 = 1293.33keV SHAPE: FWHM = 1.96 FW(1/5)M = 2.93 ID: Ar-41 at 1293.60keV Corrected Rate = 0.31 +/- 0.01 cA
- ROI # 16 RANGE: 11655 = 1456.89keV to 11711 = 1463.90keV AREA: Gross = 295 Net = 228 +/- 28 CENTROID: 11684.65 = 1460.60keV SHAPE: FWHM = 0.71 FW(1/5)M = 2.70 ID: K-40 at 1460.75keV Corrected Rate = 0.43 +/- 0.05 cA
- ROI # 17 RANGE: 11882 = 1485.30keV to 11938 = 1492.31keV AREA: Gross = 289 Net = 260 +/- 22

OID: 11915.30 = 1489.47keV

SHAPE: FWHM = 1.07

FW(1/5)M = 2.96


ID: Pr-144 at 1489.20keV

Corrected Rate = 17.33 + /- 1.47 cA

# 

-/+	49	11	36	0	30				57		-	-	1	+	7	210
Estimated Activity (Bq)	2026	2283	0	4	17	4	8	23	2368	10	6	17	0	39	58	2476
% Detector Efficiency **	3.20%	5.30%	4.60%	2.60%	2.10%	2.00%	1.62%	1.47%	1.39%	1.34%	1.28%	1.26%	1.22%	0.80%	0.74%	0.70%
-/+	1.56	0.58	1.66	0.01	0.64	0.01	0.01	0.01	0.79	0.02	0.01	0.01	0.01	0.01	0.05	1.47
<b>&amp;</b>	64.82	121.02	0	0.1	0.36	0.07	0.13	0.34	32.91	0.13	0.11	0.22	0.11	0.31	0.43	17.33
	80.12	133.53	202.12	364.48	475.35	497.08	604.66	661.62	696.49	724.18	756.72	765.82	795.76	1293.6	1460.75	1489.2
LIBRARY	Ce-144	Ce-144	U-235	I-131	Cs-134	Ru-103	Cs-134	Cs-137	Pr-144	Zr-95	Zr-95	Nb-95	Cs-134	Ar-41	K-40	Pr-144
FW(1/5)M LIBRARY ( keV)	1.55	1.65	0.38	1.98	0.32	1.48	1.91	2.2	2.38	2.48	2.25	2.29	2.26	2.93	2.7	2.96
FWHM	66'0	1.06	0.23	1.28	0.16	0.76	1.33	1.39	1.64	1.7	1.04	1.54	1.66	1.96	0.71	1.07
CENTROID FWHM	80.55	133.9	199.49	364.7	467.66	511.84	604.52	661.51	696.31	723.69	756.63	765.6	795.59	1293.33	1460.6	1489.47
-/+	125	311	83	48	47	26	49	29	59	37	38	47	40	44	28	22
	5186	65352 311	-136	389	26	290	641	1458	2452	279	297	1075	484	1522	228	260
GROSS NET	8889	75444	1916	870	481	851	996	1813	2630	477	483	1261	670	1584	295	289
( keV)	81.94	135.36	201.15	366.84	469.75	513.96	99.909	663.88	698.74	726.61	759.1	9'.292	798.34	1297.12	1463.9	1492.31
RANGE	79.19	132.37	197.9	363.09	465.5	509.47	601.91	658.88	693.74	721.61	753.85	762.35	793.09	1290.61	1456.89	1485.30
KOI#	<del></del>	7	m	4	2	9	7	8	6	10	11	12	13	14	15	16

No accurate geometric efficiency is available for assay. Detector Efficiency has been used for 10 ml vial. \*




Page 7 of 10


Detector #1 ACQ 20-Jan-2003 at 17:56:37 RT = 5111.6 LT = 5000.0 DSPE-218 bird2 ROI # 1 RANGE: 627 = 79.41 keV to 655 = 82.90 keVAREA : Gross = 1288 Net = 925 +/- 48CENTROID: 641.63 = 81.23 keVSHAPE: FWHM = 0.76 FW (1/5)M = 1.47ID: Ce-144 at 80.12keV Corrected Rate = 11.56 +/- 0.60 cA RANGE: 1053 = 132.51keV to 1083 = 136.25keV ROI # 2 AREA : Gross = 12118 Net = 11405 +/- 119CENTROID: 1068.88 = 134.49 keVSHAPE: FWHM = 1.04 FW (1/5) M = 1.64ID: Ce-144 at 133.53keV Corrected Rate = 21.12 +/- 0.22 cA RANGE: 1150 = 144.61 keV to 1180 = 148.35 keVROI # 3 AREA: Gross = 220 Net = 80 +/- 25 CENTROID: 1166.87 = 146.71 keVSHAPE: FWHM = 0.48 FW (1/5)M = 0.67ID: Ce-141 at 145.45keV Corrected Rate = 0.03 + / - 0.01 cA ROI # 4 RANGE: 2255 = 282.41keV to 2289 = 286.65keV AREA : Gross = 166 Net = 43 +/- 25CENTROID: 2277.89 = 285.27 keVSHAPE: FWHM = 0.16 FW(1/5)M = 0.78No close library match. ROI # 5 RANGE: 2897 = 362.50keV to 2933 = 366.99keV AREA : Gross = 1009 Net = 886 + /- 39CENTROID: 2914.40 = 364.67 keVSHAPE: FWHM = 1.24FW(1/5)M = 2.00ID: I-131 at 364.48keV Corrected Rate = 0.22 + / - 0.01 cA ROI # 6 RANGE: 3192 = 399.31keV to 3228 = 403.80keV AREA : Gross = 72 Net = -8 +/- 20 CENTROID: 3200.00 = 400.30 keVSHAPE: FWHM = 1.40 FW(1/5)M = 1.52No close library match. RANGE: 3547 = 443.60keV to 3583 = 448.10keV ROI # 7 AREA : Gross = 49 Net = 0 +/- 15 CENTROID: 3564.70 = 445.81 keVSHAPE: FWHM = 0.31 FW(1/5)M = 0.43ID: Ba-140 at 437.55keV Corrected Rate = 0.00 + / - 0.19 cA ROI # 8 RANGE: 4484 = 560.55 keV to 4524 = 565.55 keV+/- 17 AREA: Gross = 57 Net = 2 CENTROID: 4506.14 = 563.32 keVSHAPE: FWHM = 0.18 FW(1/5)M = 0.31ID: Cs-134 at 563.26keV Corrected Rate = 0.00 + / - 0.04 cA

ROI # 9 RANGE: 4815 = 601.88 keV to 4857 = 607.12 keV
AREA: Gross = 98 Net = 76 +/- 14
CENTROID: 4836.96 = 604.62 keV
SHAPE: FWHM = 1.05 FW(1/5)M = 1.31
ID: Cs-134 at 604.66 keV
Corrected Rate = 0.02 +/- 0.00 cA

- ROI # 10 RANGE: 5075 = 634.34keV to 5115 = 639.33keV AREA: Gross = 73 Net = 46 +/- 14 CENTROID: 5093.89 = 636.70keV SHAPE: FWHM = 0.22 FW(1/5)M = 0.95 No close library match.
- ROI # 11 RANGE: 5274 = 659.19keV to 5316 = 664.43keV AREA: Gross = 207 Net = 171 +/- 19 CENTROID: 5292.46 = 661.49keV SHAPE: FWHM = 0.81 FW(1/5)M = 1.97 ID: Cs-137 at 661.62keV Corrected Rate = 0.04 +/- 0.00 cA
- ROI # 12 RANGE: 5544 = 692.90keV to 5586 = 698.15keV AREA: Gross = 399 Net = 320 +/- 28 CENTROID: 5571.38 = 696.32keV SHAPE: FWHM = 1.08 FW(1/5)M = 1.96 ID: Pr-144 at 696.49keV Corrected Rate = 4.30 +/- 0.38 cA
- ROI # 13 RANGE: 6108 = 763.34keV to 6152 = 768.84keV AREA: Gross = 25 Net = 17 +/- 8 CENTROID: 6129.83 = 766.07keV SHAPE: FWHM = 0.20 FW(1/5)M = 0.47 ID: Nb-95 at 765.82keV Corrected Rate = 0.00 +/- 0.00 cA
- ROI # 14 RANGE: 6343 = 792.70keV to 6387 = 798.20keV AREA: Gross = 61 Net = 16 +/- 17 CENTROID: 6364.34 = 795.36keV SHAPE: FWHM = 0.29 FW(1/5)M = 0.43 ID: Cs-134 at 795.76keV Corrected Rate = 0.00 +/- 0.00 cA



Page 10 of 10



Are you able to advise me on the following questions?

Back in July last year there was an accident at ANSTO in the spent fuel cooling pond, I think it was in building 23. The pool was contaminated following an incorrect cropping incident. Am I correct in understanding that the pond is still too contaminated for it to be used to store any additional spent fuel rods since the incident?

00

If so, how are these highly radioactive rods being stored?


Are they being stored in a situation that has been licensed by ARPANSA? If not has ARPANSA been asked to licence such storage?

When is it anticipated that the pond will be able to be used for its licenced task?

Is ARPANSA able to carry out random, unannounced inspections at ANSTO if it believed that unlicensed activities were being carried out at the site - i.e. as in Iraq for instance? I seem to recall that when the ARPANS Act was up for public examination, inspections had to be requested in advance - and that I objected to this as being 'too polite'.

I have heard that there have been incidents of birds (pigeons) being able to fly in and out of building 23 (?) and being found later lying with feet pointing to heaven, dead. This reminds me of a similar situation at Sellafield when the public was warned not to touch dead birds in the vicinity of the plant. In a bizarre twist, the story from ANSTO is that, as no-one knows what to do with them, the birds are 'lying in a cupboard'.

Is there anything in the licensing of the plant to protect native fauna? Should the public be warned?



Regards,



### **Meeting on B23 Cropping Pond Incident**

Date: 11 April 2003 Time: 10 am

Venue: Regulatory Branch Conference Room

Present:

Sh

s 47F persona

s 47F personal

### **Background Information**

B23 Cropping Pond is licensed as a nuclear installation under Facility Licence FO0044-4C. An incident involving cropping an irradiated fuel occurred on 15 March 2002. ANSTO informed ARPANSA of the incident within 24 hours. ARPANSA Regulatory Branch Staff made several visits and meet ANSTO staff to follow up this incident. ARPANSA received the final report on the incident from ANSTO on 18 March 2003.

### **Discussion Points**

- 1. Discussion took place in the light of the Final Report of Cropping Pond Incident submitted to ARPNASA.
- 2. It was agreed to keep records of every visit, meeting, discussion and any other communication relevant to any facility in an appropriate format.
- 3. It was agreed to conduct a two-phase inspection, one covering the health physics aspect and the other covering the engineering aspect.

  s 47F personal will conduct the inspection on health physics aspect and Engineering aspect. Details of the inspection will be finalised by these two inspection teams.
- 4. The purpose and scope of health physics aspects will include:
  - Health physicists involved in providing health physics service; are they qualified and/or accredited?
  - Was there any off-site contamination? If so, why wasn't it reported?
  - Waste generation from the decontamination process.
  - Contamination problems involving birds.
  - Control measures.
  - Operational and radiological protection procedures.
- 5. The proposed time for inspection covering health physics aspect is first week of May 2003.

# **FILE NOTE**

File Name: Radiation Regulation- Compliance Surveillance - Reports Planus Insection, facility Line Floorey-40	File Number: 52003/00283
Name: Organisation: $A_{NS70}$	Phone Number: s 47F personal
Date: 26/05/03	Time: 2:45am/pm Duration: 1
Incoming Call	Drafting

Perusing

Researching

Conferences

Outgoing Call

Internal Call

Attendance on Associate

Attendance on Client

Talked & Stranday requesting the gamma Guetanapy results of two dead seins personal reform to the NT for this matter. Salveymently I talked & marked & the morning of the form of the form of the marked & marked & the morning and get dear & me sometime in the laste afternoon today.

**ARPANSA Action Required:** 

Officer:

Signature

Date: 26/05/03

AUSTRALIAN RADIATION PROTECTION AND NUCLEAR SAFETY AGENCY

# **FINAL INSPECTION REPORT**

**RB-INS-03-03** 

Licence Holder: ANSTO

Date of inspection: 14 May 2003

Licence No: FO0044-4C


Location: Lucas Heights

# **ANSTO Fuel Operations Facility**

**Building 23 Cropping Pond and Spent Fuel Storage in Irradiation Pond** 

**REGULATORY BRANCH** 

**June 2003** 



### 1. INTRODUCTION

### 1.1 PURPOSE AND SCOPE OF INSPECTION

The purpose and scope of the inspection was to check the compliance of operation with the standard licence conditions [3], special licence conditions of the Operating Licence [2] and recommendations for improvement set out in the ARPANSA Safety Evaluation Report [4].

# 1.2 LEGISLATION OR OTHER REGULATORY REQUIREMENTS RELEVANT TO THIS INSPECTION

According to Section 35 [35(1) and 35(2)] of the Act a controlled facility is subjected to an inspection to check the compliance with the licence conditions. Therefore, a planned inspection was conducted at ANSTO Fuel Operations Facility to confirm the compliance with the licence conditions.

### 1.3 Documents

The documents sighted during the inspection included:

- (a) Fuel Management and Active handling Instruction, NFI 9.7.38
- (b) Memorandum of Understanding between Waste Operations and Technology Development (WOTD) and Fuel Management and Active Handling (FMAH) Section (November 2001)
- (c) Maintenance Procedure for Fuel management and Active Handling, NFP 9.8
- (d) Service Level Agreement between Engineering and Nuclear Technology, SH 113932 (November 2002, valid until June 2004)
- (e) Organisational chart of Nuclear Technology (November 2002, renewal subject to annual review)
- (f) Memorandum of Understanding between Fuel Management and Active Handling Section and Radiation Technology Group (February 2001, renewal subject to annual review)
- (g) Training Procedure NWP 18.1
- (h) Training and Accreditation for WOTD Operators NWP 18.2
- (i) Gross alpha- and beta-activity distribution during 05 March 2002 to 05 May 2003 at B23 gamma Pond
- (j) Results obtained from dipstick analysis of B23 Irradiation-Liner and B23 Cropping-liner
- (k) ANSTO Internal Independent Investigation report of B23 Cropping Pond Incident (B23 Cropping Pond Incident March 2002, A investigation by 2002). (Note: Marked "Private and Confidential").

### 1.4 Interviews

The following ANSTO staff members were present at the Entrance and Exit meeting:



### 1.5 Plant and Equipment

The following units of Fuel Operations and its adjacent establishments inspected:

- B23 Cropping Pond
- B23 Irradiation Pond

### 1.6 Demonstrations

During the conduct of the radiation survey of B23 Cropping Pond and its perimeter, radiation surveys were conducted and contamination control measures implemented.

### 2. INSPECTION FINDINGS

### **Effective control**

Std LC <sup>1</sup>	Sp LC <sup>2</sup>	Items	Compliance	Findings/Observations
	3.5	Service level	Satisfactory	The available service agreements were sighted and were acceptable to
		agreements		ARPANSA. Improvement to the memorandum of understanding between
				Fuel Operations and Safety and Radiation Sciences should be made in the
				form of a formal service level agreement.
5		Personal	Satisfactory	Training records are available. Certificates are awarded to the successful
		training		candidates as recognition of the completion of the training course. There
				are six trained operators in FMAH.
6		Operator	Satisfactory	An accreditation process is in place. Fuel Operations is in the process of
		accreditation		revisiting the word 'accreditation' in terms of competency. It is
				recommended to involve ARPANSA Regulatory Branch staff during the
				accreditation interview for some key personnel. It is recommended to
				include lessons learnt from the incident in the retraining and accreditation
				program.

<sup>&</sup>lt;sup>1</sup> Std LC means Standard Licence Condition set out in the ANSTO Handbook

<sup>&</sup>lt;sup>2</sup> Sp LC means Special Licence Condition set out in the Facility Licence

Abnormal occurrences, Incidents and Accidents

Std LC	Items	Compliance	Findings/Observations
18	Abnormal occurrences, incidents and accidents	To be determined subject to regulatory	There was an incident on 15 March 2002 during cropping of a spent fuel element. ARPANSA was notified about the incident. ARPANSA received the Final Report on the incident from ANSTO on 18 March 2003. State of the Final Report carried out an internal independent investigation and prepared the report on 31 July 2002 of this
		review of all reports	incident and ARPANSA inspectors received a copy of this report in confidence during the inspection. Fuel cropping operation has been suspended since the incident. It is recommended to provide to ARPANSA the dose estimation and dose calculation procedure for the abnormal occurrences, incidents and accidents.
19	Reporting of abnormal occurrences, incidents and accidents	To be determined subject to regulatory review of all reports	ANSTO event report system applies (SD 2.4). See comment above under Standard Licence Condition 18. No clear information on contamination control measures was available in the final report on the incident submitted by ANSTO. It is recommended to include comprehensive contamination-control measures while dealing with abnormal occurrences, incidents and accidents. ARPANSA should be notified prior to the recommencement of the normal operation of B23 cropping pond and relevant updated procedures for B23 cropping pond operation should be subject to ARPANSA examination. ANSTO informed that two dead birds with traces of contamination of Cs-134 and Cs-137 were found in the vicinity of the B23 cropping pond and the bird were subject to gamma-spectroscopy. ARPANSA have requested the copies of the gamma-spectroscopy results.
20(iv)	Records of abnormal occurrences, incidents and accidents	Satisfactory	Details of the records of abnormal occurrences, incidents and accidents were available and the records were in an appropriate quality system.

**Radiation Protection Arrangements** 

	Radiation Protection Arrangements							
Std LC	Sp LC	Remdn3	Items	Compliance	Findings/Observations			
30	Spie	Acting to the second se	Radiation protection of employees & others	Satisfactory	Arrangements and procedures for radiation protection are in place. Both administrative and engineering control are in place for radiation protection. Access to the B23 cropping pond is restricted. Two swallows were observed flying out of the building. The roller doors of B23 bay were found open. The cropping pond is covered with corrugated plastic sheet and synthetic net to prevent birds' access to the pond. The measured gamma radiation dose at wall height near the cropping pond was 2.6 mSv/hr as on 06 May 2003. The recent value of total beta activity in the cropping pond area was in the range of 250-500 MBq/m³. It is recommended to provide the weekly results of Maypack			
	3.9	4.2.1.5(b)	Radiological safety procedures/ instructions  Use of radiation & contamination working notices	Satisfactory	sample of B23 cropping pond to ARPANSA.  Local rules and procedures for radiological safety are in place. The local rules and procedures are implemented by the Area Supervisor and Radiation Protection Adviser. Visitors are always escorted by the Health Physics Surveyor. Clear signage of restriction on entry is in place Health Physics Surveyor is always available on-site during operation of the pond.  Working areas in the B23 copping pond is classified as blue contamination and blue radiation area. Controlled areas in the B23 cropping pond are delineated by physical means. Relevant health physics requirements and works instructions are followed to control contamination			

<sup>&</sup>lt;sup>3</sup> Romdn means recommendations for improvement set out in the ARPANSA Safety Evaluation Report

### **Radioactive Waste**

Std LC	Sp LC	Remdn	Item	Compliance	Findings\Observations
48	3.11	4.2.1.6(a)	Arrangements	Satisfactory	NFP 9.12 is referred to for arrangements and
			and procedures		responsibilities of waste management. SD 5.7 applies
1			for radioactive		to characterisation of wastes and final characterisation
			waste		is done by WOTD. A database for radioactive waste is
					available, developed with the assistance of the ANSTO
					Information Technology.

### **Environmental Monitoring**

Sp LC	Item	Compliance	Findings\Observations
3.12	Groundwater monitoring	Satisfactory	There are two bore holes (MW11, MW14) in the vicinity of the B23 cropping pond. The sample analysis is done through the ANSTO EMAP system and ANSTO Environment uses their QA system for this purpose. It was informed that no activity was detected in the results of the last quarter. The liner sump samples are analysed by the Nuclear Technology and the results of the last one year 05 May 2002-05 May 2003) was provided to ARPANSA during the inspection Previously, the outside liner results showed the presence of low activity which may have been due to cross contamination.

### Security

Remdn	Item	Compliance	Findings\Observations
4.2.1.7(c)	Entry	Satisfactory	Appropriate security arrangements are in place.
	restrictions		

### 3. CONCLUSIONS

The available arrangements and procedures in the inspected areas as described in Section 2 were found satisfactory except for abnormal occurrences, incidents and accidents. ARPANSA will review the arrangements and procedures pertaining to abnormal occurrences, incidents and accidents including the final report (18 March 2003) and internal investigation report (31 July 2002) of an incident (15 March 2002) involving cropping of a spent fuel element. Generally, the staff consulted were found knowledgable and responsive about the facility and regulatory affairs.

### **COMPLIANCE**

The operation of the facility complies with the relevant standard and special licence conditions as described in Section 2 of this report. With regard to Licence Holder response and reporting to ARPANSA, Regulatory Branch will review the Final Incident Report (14 March 2003) and the internal ANSTO investigation report (31 July 2002) and advise the CEO of any further actions or follow up are required.

### NON-COMPLIANCE

No item was identified as being in non-compliance with the licence conditions during the inspection

### MATTERS FOR CONSIDERATION BY THE LICENCE HOLDER

The inspectors found that the following matters should be taken into account by the Licence Holder in operating the facility.

- 1. The memorandum of understanding between ANSTO Fuel Operations and Radiation and Safety Science should be in the form of formal service level agreement.
- 2. ARPANSA Regulatory Branch staff should be invited to participate as observer during the accreditation interviews for one or two key operating personnel. (See findings Section 2, Std LC 6).
- 3. Lessons learn from the incident should form part of the retraining and accreditation process. (See findings Section 2, Std LC 6).
- 4. Dose estimation and dose calculation procedures for the abnormal occurrences, incidents and accidents should be provided to ARPANSA. (See findings Section 2, Std LC 18).
- 5. ARPANSA should be notified prior to the recommencement of the normal operation of B23 cropping pond and relevant updated procedures for B23 cropping pond operation should be subject to ARPANSA examination. (See findings Section 2, Std LC 19).
- 6. The gamma-spectroscopy results of the two dead birds should be provided to ARPANSA. (See findings Section 2, Std LC 19).
- 7. There should be better control for opening and closing of the roller door of B23 Bay with the door remaining closed as often as practicable to prevent entry of birds. (See findings Section 2, Std LC 30).
- 8. A representative few weekly results of Maypack sample of B23 cropping pond should be provided to ARPANSA. (See findings Section 2, Std LC 30).

### **INSPECTORS**

Name:
Signat

Date: 16/06/03

Name: Signature b = b = b = b

MDEXED 49

F11329

Moved from

S2002/00258

S 47F personal

Subject: Updates please


s 47F personal as discussed, some responses to s 47F personal queries

Could you please let me know the outcome of the ARPANSA investigations into the condition of the spent fuel cooling pond that was contaminated almost a year ago? Has it been cleared for normal use yet?

The B23 croping pond remains out of service. ARPANSA officers inspected the area in May 2003 and were satisfied that appropriate effective control, radiation safety and contamination control measures were in place. ARPANSA will conduct further inspections prior to the facility being returned to normal operation, probably in late 2003.

Associated with this there was the matter of the dead birds. Were they affected by radiation within the pond building and if so what effect would this have on the ANSTO workers in that area?

ANSTO informed ARPANSA that two dead birds were found in the vicinity of the B23 cropping pond in January 2003. The birds were subject to gamma-spectroscopy with traces of contamination found that would be attributable to the birds having access to the B23 cropping pond. From the results, ARPANSA is satisfied that the contamination was very low level and could not have contributed to the birds' demise. Further ARPANSA is satisfied that ANSTO has subsequently taken measures to prevent access by birds to the cropping pond.



on 11/06/2003 16:56

on 11/06/2003 16:35:28

Forwarded by


To: s 47F personal cc:

Subject: Updates please

Dear s 47F personal

Could you please let me know the outcome of the ARPANSA investigations into the condition of the spent fuel cooling pond that was contaminated almost a year ago? Has it been cleared for normal use yet?

Associated with this there was the matter of the dead birds. Were they affected by radiation within the pond building and if so what effect would this have on the ANSTO workers in that area?



Regards,

s 47F personal
- att1.htm



To: s 47F personal cc:

Subject: Updated information

Dear s 47F personal

Not an TRIP

s 47F personal has asked me to reply to your email of June 11 requesting updated information on three things:

- 1. ARPANSA investigations into the Building 23 fuel rod cropping pond contamination that occurred in March 2002;
- 2. Dead birds found by ANSTO workers within the same building; and

s 22(1)(ii) irrelevant

Firstly, the Building 23 croping pond remains out of service. ARPANSA officers inspected the area in May 2003 and were satisfied that appropriate effective control, radiation safety and contamination control measures were in place. ARPANSA will conduct further inspections prior to the facility being returned to normal operation, probably in late 2003.

Secondly, ANSTO informed ARPANSA that two dead birds were found in the vicinity of the Building 23 cropping pond in January 2003. The birds were subject to gamma-spectroscopy with traces of contamination found that would be attributable to the birds having access to the pond. Nonetheless, ARPANSA is satisfied that the contamination was very low level and could not have contributed to the birds' demise. ARPANSA is also satisfied that ANSTO has subsequently taken measures to prevent access by birds to the cropping pond.



I trust the information provided is of assistance.

Regards,

s 47F personal

**Public Affairs Officer** 

Australian Radiation Protection & Nuclear Safety Agency

Phone: s 47F personal

6. Einlitung 25 Pond continues to be an essee howard it has not get her cleaned up. I was importanted that there is a proper in Building 25 contaming frozen bards. There birds have apparently have remembered in the But 20 12nd and he come continued It was not much him for the bird of whiteen you had been killed to prove contamination spread

s 47F personal

( see wee.)