



INSPECTION REPORT

Licence Holder: Australian Customs and Border Protection Service	Licence Number: F0131
Location inspected: 4-10 Mullally Close, West Melbourne, VIC	Date of inspection: 4 August 2011
	Record No: R11/13024
<p>This inspection was conducted under Part 7 of the <i>Australian Radiation Protection and Nuclear Safety Act 1998</i> (the Act). The purpose of the inspection was a routine audit of Australian Customs and Border Protection Service (Customs) Melbourne Container Examination Facility.</p> <p>The inspection consisted of the following:</p> <ul style="list-style-type: none">• Discussions with Customs representatives• Review of Customs quarter yearly reports to ARPANSA• Review of training records of Customs personnel• Review of competency certification of service engineers engaged by Customs• Verification that work procedures are in place• Review of radiological survey reports and routine maintenance reports• Verification of radiation survey meter calibration records• Physical inspection of the container examination scanning hall, including taking appropriate photographs. <p>Findings:</p> <ul style="list-style-type: none">• Quarter year reports containing information about compliance were submitted to ARPANSA by the due date.• Operators of the controlled facility have received appropriate training. A copy of training records was provided to the ARPANSA inspector.• The facility maintenance engineer has certification from Customs radiation safety officer as to appropriate competency and qualifications.• Appropriate work procedures are maintained and are available for use by operators.• The Customs radiation safety officer has conducted a recent radiological survey of the facility. A copy of the report was provided to the ARPANSA inspector.• The facility maintenance engineer conducted a quarterly maintenance inspection. A copy of the maintenance report was provided to the ARPANSA inspector.• Radiation warnings signs and warning lights were found to be appropriately positioned within the facility.• Emergency stop buttons and emergency pull cords were found to be appropriately positioned within the facility.• The radiation survey meter used by Customs was found to be within calibration. <p>Conclusion: No evidence of non-compliance was identified.</p>	