



# ARPANSA Inspection Outcomes

John Ward
Director, Continuous Improvement
Regulatory Services
ARPANSA

## **Regulatory Objectives**

ARPANSA's fundamental regulatory objective is to ensure that licenced facilities and sources are controlled and operated in an acceptably safe manner at all times.

ARPANSA is committed to the effective and efficient regulation. Our strategies are:

- **1. Ensure compliance** of Commonwealth entities with regulatory requirements
- 2. Ensure regulatory actions are proportionate to the risk
- 3. Provide **timely and evidence based** assessment of applications
- 4. Promote **international best practice** in regulatory policy and practices
- 5. Communication with regulated entities is clear, targeted and effective
- Contribute to the continuous improvement of regulatory framework and processes


#### **Inspection Statistics**

#### 2017/18 Figures


- 73 Inspections
  - 20 Facility
  - 53 Source
  - 2 Augmented inspections
  - 10 potential non-compliance
  - 196 areas for improvement
- 60 Site visits to facilities
- 10 confirmed non-compliance
- 32 information sharing meetings with licence holders

#### ARPANSA performance (first three quarters)

- 85% of inspections on schedule
- 88% of inspection feedback is positive
- 59% of corrective actions initiated within three months
- 20% of facility inspections used external expertise
- 76% of our direct licence holder effort was on medium or higher risk licences
- 79% of application decisions in agreed time



#### **Inspection Performance Objectives and Criteria**




- The resources applied are graded on the risk of facility:
  - inspected on between 1 and 8 baseline modules in a single inspection
  - all cross cutting modules
  - recognition of good performance

# Typical examples of inspection scope and frequency:

- OPAL Reactor (20 MW Open Pool Multipurpose Reactor)
  - 3 inspections per year -1 baseline module each
- Isotope Production Facilities
  - 1 inspection per year3 baseline modules
- 18 MeV Cyclotron
  - 1 inspection per year3 baseline modules

## **Inspection Findings**

#### **AREAS FOR IMPROVEMENT (AFI)**





- Proc/Instr not to std
- Configuration Control
- Proc/Instr not reviewed or up to date
- Proc/Instr not followed
- Records not up to date
- Safety equipment not used or to std
- Labels and signs not to std
- Hazard/risk assessment
- Poor communication
- Training inadequate
- Missed learning opportunities
- Change Control
- Accountabilities not clear
- Communication to ARPANSA

(Clockwise from top)


Data from 2016/17 (not final)

#### **AFI - BROAD CATEGORISATION**






#### **COMMON CONTRIBUTORS TO ACCIDENTS**



# **FURTHER INFORMATION**



Data on our inspection findings and other useful information is available from the ARPANSA website:

www.arpansa.gov.au





# **THANK YOU**



#### **CONTACT ARPANSA**

John.Ward@arpansa.gov.au **Email:** 

Website: www.arpansa.gov.au

**Telephone:** +61 2 9541 8350

Freecall 1800 022 333

**General Fax:** +61 2 9541 8348





