ANSTO

#### LIMITS AND CONDITIONS

## **RADIOLOGICAL HAZARDS**

LC 3.4

Rev 0

Page 1 of 2

AMENDMENT RECORD											
REV	DATE APPROVED		PAGES/SECTIONS AFFECTED		REMARKS						
0			All		New issue (DHF).	applicable	for	the	de-fuelled	HIFAR	Facility
)	5										
	$\bigcirc$						c				
CONTROLLED COPY DISTRIBUTION											
Copy No.			Holder					Location			
COPY STATUS (tick one)			CONTROLLED - COPY HOLDER NO.								
Name			Name	Signature					Position	1	Date
Prepared:		R Hutchison						Princ Lla	cipal Consu byd's Regis	lltant ter	20.00
Checked:		J	J Wernej				I	-aci	lity Super	/isor	
Appro	roved:		Sirkka					Fac	ility Mana	ger	

### LIMITS AND CONDITIONS

## **RADIOLOGICAL HAZARDS**

LC 3.4

Rev 0

#### SUBSECTION NO: 3.4.1 - AIR ACTIVITY IN BUILDING 15

#### 1. APPLICABILITY

This Limiting Condition applies whenever people are in the Reactor Building.

#### 2. OBJECTIVE

The objective of the Limiting Condition is to ensure safety of personnel inside Building 15.

#### 3. LIMITING CONDITION

The air activity in the Reactor Building atmosphere shall not exceed a contamination level of 10 DAC (tritium).



Calibration/functional testing of the tritium monitors shall be conducted annually.

# 5. ACTIONS

5.1 If the air activity in the Reactor Building atmosphere exceeds 10 DAC, personnel shall be evacuated from Building 15 within one hour.

Informative note: Procedures also require that the Facility Supervisor be informed if the airborne activity in the facility rises above 2 DAC. In such cases, the Supervisor must investigate the causes.

#### 6. BASIS

The basis of the Limiting Condition is for the Facility Supervisor to ensure personnel safety from radiological hazards. Tritium is considered as the critical indicating radionuclide, within the guideline of the ANSTO OHSE Standard (REF 2).

#### 7. **REFERENCES**

- [1] LC Subsection 3.1.1.2 "Detection of Tritium"
- [2] ANSTO OHSE Standard, Radiation Safety (AS2310), 2006
- [3] HIFAR Operations Instruction NHOI 9.2.25.8 "Instruction for Airborne and Surface Contamination Inside the RCB"
- [4] HIFAR OLC 4.17, Rev 3, Radiological Hazards, 2006 (superseded)