



## INSPECTION REPORT

<b>Licence Holder:</b> Australian Customs and Border Protection Service	<b>Licence Number:</b> F0125
<b>Location inspected:</b> Gate B15, Bumborah Road, Matraville, NSW	<b>Date of inspection:</b> 7 July 2011
<p>This inspection was conducted under Part 7 of the <i>Australian Radiation Protection and Nuclear Safety Act 1998</i> (the Act). The purpose of the inspection was a routine audit of Australian Customs and Border Protection Service (Customs) Sydney Container Examination Facility.</p> <p>The inspection consisted of the following:</p> <ul style="list-style-type: none"><li>• discussions with Customs representatives</li><li>• review of Customs quarter yearly reports to ARPANSA</li><li>• review of training records of Customs personnel</li><li>• review of competency certification of service engineers engaged by Customs</li><li>• verification that work procedures are in place</li><li>• review of radiological survey reports and routine maintenance reports</li><li>• verification of instrument calibration records</li><li>• physical inspection of the container examination scanning hall, including taking appropriate photographs.</li></ul> <p><b>Conclusion:</b> No evidence of non-compliance was identified.</p>	