



## INSPECTION REPORT

<b>Licence Holder:</b> CSIRO Earth Science and Resource Engineering	<b>Licence Number:</b> F0232
<b>Location inspected:</b> Pullenvale, QLD	<b>Date of inspection:</b> 8 March 2012
	<b>Report No:</b> R12/02607
<p>This is the record of an inspection conducted under Part 7 of the <i>Australian Radiation Protection and Nuclear Safety Act 1998</i> (the Act). The purpose of the inspection was to assess compliance with the Act, the Australian Radiation Protection and Nuclear Safety Regulations 1999 (the Regulations) and licence conditions.</p> <p>The scope of this inspection was not limited in any way. However, the inspection focussed upon licence conditions 1-7 contained within Schedule 2 of Facility Licence F0232.</p> <p>The inspection consisted of a selective examination of procedures, sources, plant and equipment, etc and associated records, interviews with personnel and inspector observations (including photographs and measurements).</p> <p>The following observations and conclusion are based on an analysis of information and evidence obtained during the inspection.</p> <p><b>Observations:</b></p> <p>The following observations were made:</p> <ul style="list-style-type: none"><li>• The personnel who used the facility had received radiation safety training.</li><li>• The hand held dose rate meters had been calibrated less than twelve months ago.</li><li>• Records indicated that checks of the facility interlocks have been performed regularly.</li><li>• Work procedures are in place.</li><li>• Records indicated that radiological surveys had been performed.</li></ul> <p><b>Conclusion:</b> At the time of inspection, there was no evidence of non-compliance.</p>	