



Australian Radiation Protection and
Nuclear Safety Agency

**ERRATA – EXPERTS MISSION TO REVIEW THE
PSAR OF THE RRR FOR ARPANSA**

**REGULATORY BRANCH, ARPANSA
26 July 2001**

Authorised:

**D I Macnab
Director**

Figures 1 and 2 provided by ANSTO and included in Appendix V - Issue Number 2 are inaccurate. ANSTO have requested that the corrected figures be included in the report. The corrected figures were provided on 17 July 2001.

The inaccuracy of the figures relates to the failure of the graphs depicted in Appendix V – Issue Number 2 to meet the y-axis at 0.3g. All other values have remained the same.

Figure 1 – Comparison between design value and disaggregated IGNS value.




Figure 2 – Comparison between design value and reduced IGNS value.

