





University of Melbourne

Parkville, Victoria 3052

11th February, 1981.



Dear

Australian Radiation Laboratory

The building recently vacated by the Australian Radiation Laboratory has been carefully monitored for residual radioactive contamination.

Only one contaminated area was detected. This was on some wood in the loft area. There was a small patch of beta-gamma contamination just above the filter block in the radium wing exhaust ducting. The contaminated wood has been removed. The remaining ducting is free from contamination (the exhaust filter had already been removed).

All other areas, including the old radium wing and safe are free of radioactive contamination.

There is no need to impose any radiological health restrictions on work in this building.

Yours sincerely,

